



Pennine Manufacturing

Heavy Duty Groundmat


Solar Tests

|

Pennine

Inspected By:

Inspection Date:	9/20/2016 1:13:25 PM	Location	
Equipment		Equipment Name:	
Ambient Air Temp:		Wind Speed	
Load (%)		Max Rated Load:	
Exception Temperature:		Potential Problem	
Recommended Action		Repair Priority:	
Emissivity:	0.99	Reflected Temperature:	20.0 °C
Camera Manufacturer	Fluke Thermography	Camera:	13061819



vt_00001.is2


Main Image Markers

Name	Temperature	Emissivity
Centerpoint	22.9°C	0.99

Pennine

Inspected By:

Inspection Date:	9/20/2016 1:26:08 PM	Location	
Equipment		Equipment Name:	
Ambient Air Temp:		Wind Speed	
Load (%)		Max Rated Load:	
Exception Temperature:		Potential Problem	
Recommended Action		Repair Priority:	
Emissivity:	0.99	Reflected Temperature:	20.0 °C
Camera Manufacturer	Fluke Thermography	Camera:	13061819



vt_00002.is2


Main Image Markers

Name	Temperature	Emissivity
Centerpoint	28.5°C	0.99

Pennine

Inspected By:

Inspection Date:	9/20/2016 1:32:48 PM	Location	
Equipment		Equipment Name:	
Ambient Air Temp:		Wind Speed	
Load (%)		Max Rated Load:	
Exception Temperature:		Potential Problem	
Recommended Action		Repair Priority:	
Emissivity:	0.99	Reflected Temperature:	20.0 °C
Camera Manufacturer	Fluke Thermography	Camera:	13061819



vt_00003.is2


Main Image Markers

Name	Temperature	Emissivity
Centerpoint	36.2°C	0.99

Pennine

Inspected By:

Inspection Date:	9/20/2016 1:39:22 PM	Location	
Equipment		Equipment Name:	
Ambient Air Temp:		Wind Speed	
Load (%)		Max Rated Load:	
Exception Temperature:		Potential Problem	
Recommended Action		Repair Priority:	
Emissivity:	0.99	Reflected Temperature:	20.0 °C
Camera Manufacturer	Fluke Thermography	Camera:	13061819



vt_00004.is2


Main Image Markers

Name	Temperature	Emissivity
Centerpoint	39.9°C	0.99

Pennine

Inspected By:

Inspection Date:	9/20/2016 1:53:32 PM	Location	
Equipment		Equipment Name:	
Ambient Air Temp:		Wind Speed	
Load (%)		Max Rated Load:	
Exception Temperature:		Potential Problem	
Recommended Action		Repair Priority:	
Emissivity:	0.99	Reflected Temperature:	20.0 °C
Camera Manufacturer	Fluke Thermography	Camera:	13061819



vt_00005.is2


Main Image Markers

Name	Temperature	Emissivity
Centerpoint	51.2°C	0.99

Pennine

Inspected By:

Inspection Date:	9/20/2016 1:55:35 PM	Location	
Equipment		Equipment Name:	
Ambient Air Temp:		Wind Speed	
Load (%)		Max Rated Load:	
Exception Temperature:		Potential Problem	
Recommended Action		Repair Priority:	
Emissivity:	0.99	Reflected Temperature:	20.0 °C
Camera Manufacturer	Fluke Thermography	Camera:	13061819



vt_00006.is2


Main Image Markers

Name	Temperature	Emissivity
Centerpoint	55.9°C	0.99

Pennine

Inspected By:

Inspection Date:	9/20/2016 2:11:51 PM	Location	
Equipment		Equipment Name:	
Ambient Air Temp:		Wind Speed	
Load (%)		Max Rated Load:	
Exception Temperature:		Potential Problem	
Recommended Action		Repair Priority:	
Emissivity:	0.99	Reflected Temperature:	20.0 °C
Camera Manufacturer	Fluke Thermography	Camera:	13061819



vt_00007.is2


Main Image Markers

Name	Temperature	Emissivity
Centerpoint	68.0°C	0.99

Pennine

Inspected By:

Inspection Date:	9/20/2016 2:16:15 PM	Location	
Equipment		Equipment Name:	
Ambient Air Temp:		Wind Speed	
Load (%)		Max Rated Load:	
Exception Temperature:		Potential Problem	
Recommended Action		Repair Priority:	
Emissivity:	0.99	Reflected Temperature:	20.0 °C
Camera Manufacturer	Fluke Thermography	Camera:	13061819



vt_00008.is2


Main Image Markers

Name	Temperature	Emissivity
Centerpoint	68.8°C	0.99

Pennine

Inspected By:

Inspection Date:	9/20/2016 2:23:14 PM	Location	
Equipment		Equipment Name:	
Ambient Air Temp:		Wind Speed	
Load (%)		Max Rated Load:	
Exception Temperature:		Potential Problem	
Recommended Action		Repair Priority:	
Emissivity:	0.99	Reflected Temperature:	20.0 °C
Camera Manufacturer	Fluke Thermography	Camera:	13061819



vt_00009.is2


Main Image Markers

Name	Temperature	Emissivity
Centerpoint	70.3°C	0.99

Pennine

Inspected By:

Inspection Date:	9/20/2016 2:35:12 PM	Location	
Equipment		Equipment Name:	
Ambient Air Temp:		Wind Speed	
Load (%)		Max Rated Load:	
Exception Temperature:		Potential Problem	
Recommended Action		Repair Priority:	
Emissivity:	0.99	Reflected Temperature:	20.0 °C
Camera Manufacturer	Fluke Thermography	Camera:	13061819



vt_00010.is2


Main Image Markers

Name	Temperature	Emissivity
Centerpoint	72.7°C	0.99

Pennine

Inspected By:

Inspection Date:	9/20/2016 2:53:27 PM	Location	
Equipment		Equipment Name:	
Ambient Air Temp:		Wind Speed	
Load (%)		Max Rated Load:	
Exception Temperature:		Potential Problem	
Recommended Action		Repair Priority:	
Emissivity:	0.99	Reflected Temperature:	20.0 °C
Camera Manufacturer	Fluke Thermography	Camera:	13061819



vt_00011.is2


Main Image Markers

Name	Temperature	Emissivity
Centerpoint	75.7°C	0.99

Pennine

Inspected By:

Inspection Date:	9/20/2016 3:39:13 PM	Location	
Equipment		Equipment Name:	
Ambient Air Temp:		Wind Speed	
Load (%)		Max Rated Load:	
Exception Temperature:		Potential Problem	
Recommended Action		Repair Priority:	
Emissivity:	0.99	Reflected Temperature:	20.0 °C
Camera Manufacturer	Fluke Thermography	Camera:	13061819



vt_00012.is2


Main Image Markers

Name	Temperature	Emissivity
Centerpoint	78.2°C	0.99

Pennine

Inspected By:

Inspection Date:	9/20/2016 4:24:33 PM	Location	
Equipment		Equipment Name:	
Ambient Air Temp:		Wind Speed	
Load (%)		Max Rated Load:	
Exception Temperature:		Potential Problem	
Recommended Action		Repair Priority:	
Emissivity:	0.99	Reflected Temperature:	20.0 °C
Camera Manufacturer	Fluke Thermography	Camera:	13061819



vt_00013.is2


Main Image Markers

Name	Temperature	Emissivity
Centerpoint	80.2°C	0.99

Pennine

Inspected By:

Inspection Date:	9/20/2016 4:25:00 PM	Location	
Equipment		Equipment Name:	
Ambient Air Temp:		Wind Speed	
Load (%)		Max Rated Load:	
Exception Temperature:		Potential Problem	
Recommended Action		Repair Priority:	
Emissivity:	0.99	Reflected Temperature:	20.0 °C
Camera Manufacturer	Fluke Thermography	Camera:	13061819



vt_00014.is2

Main Image Markers

Name	Temperature	Emissivity
Centerpoint	81.0°C	0.99